

DPS120H - AUTOMOBILE BODY PARTS - FORD, or equal ORIGINAL EQUIPMENT PARTS BID FORM					
Description	Estimated Annual Usage	Catalog Price	Discounted Percentage	Discounted Unit Price	Extended Price
2009 Crown Victoria Police Interceptor					
Left side head light Assembly - Part #: 6W7Z-13008-BA or equal	20	\$10269	%	\$9032	\$180640
Right side head light assembly - Part #: 6W7Z-13008-AA or equal	20	\$10264	%	\$9032	\$180640
Left front fender - Part #: 7W7Z-16008-A or equal	40	\$38713	%	\$25571	\$1022840
Right front fender - Part #: 7W7Z-16008-A or equal	40	\$38713	%	\$25571	\$1022840
Hood - Part #: 6W7Z-16612-A or equal	40	\$45753	%	\$30492	\$1207880
Hood latch - Part #: 6W7Z-16700-A or equal	10	\$4680	%	\$3042	\$30420
Radiator - Part #: 6W7Z-8005-ACP or equal	40	\$21575	%	\$15426	\$617040
Complete grill - Part #: 6W7Z-8200-BAE or equal	40	\$23133	%	\$15268	\$610720
Rear bumper - Part #: 6W7Z-17K835-APTJ or equal	40	\$50903	%	\$44799	\$1791760
Bumper cover (plastic) - Part #: 3W7Z-17008-AA or equal	60	\$17651	%	\$14567	\$874020
Trunk lid - Part #: F8AZ-8440110-BA or equal	20	\$55582	%	\$36604	\$733680
Condenser - Part #: 6W7Z-16712-A or equal	20	\$36854	%	\$26351	\$527020
Wiper - Part #: 6W7Z-8B668-AC or equal	20	\$19614	%	\$10788	\$215760
Maple - Part #: 6W7Z-5404474-AB or equal	20	\$62960	%	\$41554	\$831080
Processor - Part #: 6W7Z-13C768-C or equal	20	\$59827	%	\$29619	\$592280
Left side rear tail light assembly - Part #: 6W7Z-13405-AA or equal	20	\$25612	%	\$16902	\$338140
2010 Explorer					
Left side head light Assembly - Part #: 7L2Z-13008-BA or equal	20	\$105825	%	\$69845	\$139690
Right side head light assembly - Part #: 7L2Z-13008-AA or equal	20	\$105820	%	\$69841	\$1396820
Left front fender - Part #: 8L2Z-16008-AA or equal	40	\$3395	%	\$22404	\$896160
Right front fender - Part #: 8L2Z-16005-AA or equal	40	\$3395	%	\$22404	\$896160
Hood - Part #: 8L2Z-16612-AA or equal	40	\$80603	%	\$53198	\$2127920
Hood latch - Part #: 8L2Z-16700-AA or equal	10	\$5148	%	\$3398	\$33980
Complete grill - Part #: 7L2Z-8200-BA or equal	40	\$54110	%	\$35713	\$1428520
Rear bumper - Part #: 7L2Z-17E855-A or equal	40	\$13732	%	\$9063	\$362520
Bumper cover (plastic) - Part #: 1L2Z-17K835-LA or equal	60	\$30700	%	\$27016	\$1620960
Tailgate - Part #: 8L2Z-7840010-AA or equal	20	\$80793	%	\$53324	\$1066480
Radiator - Part #: 8L2Z-8005-ACP or equal	20	\$25672	%	\$18358	\$367160

RECEIVED
 DIVISION
 FEB - 8 A 11: 29

DPS1208 - AUTOMOBILE BODY PARTS - FORD, or equal ORIGINAL EQUIPMENT PARTS BID FORM				
Condenser - Part #: 8L2Z-10712-AA or equal	20	23646	% 16907	\$ 33810
Processor - Part #: 8S4Z-13C788-A or equal	20	31996	% 15838	\$ 31676
Module - Part #: 8L2Z-76044A74-AC or equal	20	73597	% 4857	\$ 97148
Wheel Assy. - Part #: 7L2Z-76043B13-AC or equal	20	62352	% 41146	\$ 82292
Left side rear (air light assembly - Part #: 8L2Z-13405-CA or equal	20	10749	% 9459	\$ 18918
2010 Expedition				
Left side head light Assembly - Part #: 7L1Z-1300B-DB	20	30687	% 20253	\$ 40506
Right side head light assembly - Part #: 7L1Z-1300B-CB or equal	20	30702	% 20263	\$ 40526
Left front fender - Part #: 7L1Z-1600B-A or equal	40	34397	% 22702	\$ 9080
Right front fender - Part #: 7L1Z-1600S-A or equal	40	34397	% 22702	\$ 9080
Hood - Part #: 7L1Z-16812-A or equal	40	86835	% 5731	\$ 22924
Hood latch - Part #: 7L1Z-1d700-A or equal	10	4372	% 2885	\$ 2885
Complete grill - Part #: 7L1Z-8200-CPTM or equal	40	23668	% 1562	\$ 62484
Rear bumper - Part #: 7L1Z-1790B-C or equal	40	38795	% 25605	\$ 10242
Bumper cover (plastic) - Part #: 7L1Z-17K835-CA or equal	80	34587	% 2287	\$ 13696
Tailgate - Part #: 8L1Z-7840010-A or equal	20	119593	% 98732	\$ 19746
Front End - Part #: 9L1Z-16150-A or equal	20	34627	% 22854	\$ 4570
Radiator - Part #: 7L1Z-8005-A or equal	20	40091	% 2865	\$ 5733
Condenser - Part #: AL1Z-10712-A or equal	20	27703	% 19808	\$ 3961
Module - Part #: AL1Z-15044A74-AC or equal	20	62833	% 44720	\$ 8954
Processor - Part #: 8S4Z-13C788-A or equal	20	31996	% 15838	\$ 31676
Left side rear (air light assembly - Part #: 7L1Z-13405-AA or equal	20	10205	% 6735	\$ 1347
Bidder/Vendor Information:				
Name: _____				
Address: _____				
Phone: _____				
Email Address: _____				
Contract Coordinator Information:				
Name: _____				
Address: _____				
Phone: _____				
Email Address: _____				

377239 90

* Estimated quantities are for bidding and evaluation purposes only - not a guaranteed order quantity - more or less may be purchased

DPS1208 - AUTOMOBILE BODY PARTS - FORD, or equal ORIGINAL EQUIPMENT PARTS BID FORM				
Condenser - Part #: 8L2Z-10712-AA or equal	20	23646	% 16907	\$ 338112
Processor - Part #: 8S4Z-13C788-A or equal	20	31996	% 15838	\$ 316760
Module - Part #: 8L2Z-78044A74-AC or equal	20	37597	% 49574	\$ 911482
Wheel Assy. - Part #: 7L2Z-78043B13-AC or equal	20	62342	% 21146	\$ 822920
Left side rear tail light assembly - Part #: 8L2Z-13405-CA or equal	20	10749	% 9459	\$ 189182
2010 Expedition				
Left side head light Assembly - Part #: 7L1Z-13008-0B	20	30687	% 20253	\$ 405062
Right side head light assembly - Part #: 7L1Z-13008-C9 or equal	20	30702	% 20263	\$ 405260
Left front fender - Part #: 7L1Z-16008-A or equal	40	34397	% 22702	\$ 908082
Right front fender - Part #: 7L1Z-16005-A or equal	40	34397	% 22702	\$ 908082
Hood - Part #: 7L1Z-16512-A or equal	40	86835	% 57311	\$ 2292492
Hood latch - Part #: 7L1Z-10700-A or equal	10	4372	% 2885	\$ 28850
Complete grill - Part #: 7L1Z-8200-CPTM or equal	40	23668	% 15621	\$ 624842
Rear bumper - Part #: 7L1Z-17908-C or equal	40	38795	% 25665	\$ 102420
Bumper cover (plastic) - Part #: 7L1Z-17K835-CA or equal	60	34587	% 22877	\$ 1369620
Tailgate - Part #: 8L1Z-7840010-A or equal	20	149593	% 98732	\$ 1974620
Front End - Part #: 8L1Z-16138-A or equal	20	34627	% 22854	\$ 457080
Radiator - Part #: 7L1Z-8005-A or equal	20	40091	% 28865	\$ 573302
Condenser - Part #: AL1Z-10712-A or equal	20	27703	% 19803	\$ 396160
Module - Part #: AL1Z-15044A74-AC or equal	20	67833	% 44770	\$ 89540
Processor - Part #: 8S4Z-13C788-A or equal	20	31996	% 15838	\$ 316760
Left side rear tail light assembly - Part #: 7L1Z-13405-AA or equal	20	10205	% 6735	\$ 134700
Failure to include Ford or equal part information				
Bidder / Vendor Information:				
Name: <u>Midway Ford Inc</u>				
Address: <u>201 Woodland Park Rd</u>				
<u>Midway, MO 64578</u>				
Phone: <u>304-562-2715</u>				
Email Address: <u>parts@midway-ford.com</u>				
Contract Coordinator Information:				
Name: _____				
Address: _____				
Phone: _____				
Email Address: _____				

377239 90

* Estimated quantities are for bidding and evaluation purposes only - not a guaranteed order quantity - more or less may be purchased

DPB1208 - AUTOMOBILE BODY PARTS - FORD, or equal ORIGINAL EQUIPMENT PARTS BID FORM					
Description	Extended Annual Usage	Gaining Price	Discounted Percentage	Discounted Unit Price	Extended Price
2010 Crown Victoria Police Interceptor					
Left side head light Assembly - Part #: 6W7Z-13008-BA or equal	20	\$10264	% 9032	\$9032	\$180640
Right side head light assembly - Part #: 6W7Z-13008-AA or equal	20	\$10264	% 9032	\$9032	\$180640
Left front fender - Part #: 7W7Z-16008-A or equal	40	\$3878	% 25521	\$2892	\$1022840
Right front fender - Part #: 7W7Z-16005-A or equal	40	\$3878	% 25521	\$2892	\$1022840
Hood - Part #: 6W7Z-16012-A or equal	40	\$4575	% 30192	\$3192	\$1207880
Hood latch - Part #: 6W7Z-16700-A or equal	10	\$468	% 3042	\$3042	\$30420
Radiator - Part #: 6W7Z-8005-ACP or equal	40	\$2155	% 25426	\$1612	\$617040
Complete grill - Part #: 9W7Z-8200-BA2 or equal	40	\$23133	% 25268	\$1732	\$610720
Rear bumper - Part #: 6W7Z-17K835-APT0 or equal	40	\$50903	% 44799	\$28000	\$1791760
Bumper cover (plastic) - Part #: 3W7Z-17808-AA or equal	60	\$17651	% 4567	\$14567	\$874020
Trunk lid - Part #: FBAZ-6440110-BA or equal	20	\$55582	% 36624	\$36624	\$733680
Condenser - Part #: 6W7Z-16712-A or equal	20	\$36854	% 26351	\$26351	\$527020
Relay - Part #: 6W7Z-68656-AC or equal	20	\$1964	% 10788	\$10788	\$215760
Module - Part #: 6W7Z-5404A74-AB or equal	20	\$62960	% 41554	\$36900	\$831080
Processor - Part #: 6W7Z-13C786-C or equal	20	\$59821	% 29614	\$29614	\$592280
Left side rear tail light assembly - Part #: 6W7Z-13405-AA or equal	20	\$2562	% 16902	\$16902	\$338140
2010 Explorer					
Left side head light Assembly - Part #: 7L2Z-13008-BA or equal	20	\$105825	% 69845	\$69845	\$139690
Right side head light assembly - Part #: 7L2Z-13008-AA or equal	20	\$105825	% 69845	\$69845	\$1396820
Left front fender - Part #: 6L2Z-16008-AA or equal	40	\$3395	% 22404	\$22404	\$896160
Right front fender - Part #: 6L2Z-16005-AA or equal	40	\$3395	% 22404	\$22404	\$896160
Hood - Part #: 6L2Z-16012-AA or equal	40	\$8063	% 53198	\$53198	\$2127920
Hood latch - Part #: 6L2Z-16700-AA or equal	10	\$5148	% 3398	\$3398	\$33980
Complete grill - Part #: 7L2Z-8200-BA or equal	40	\$54110	% 35713	\$35713	\$1428520
Rear bumper - Part #: 7L2Z-17E655-A or equal	40	\$13732	% 9063	\$9063	\$362520
Bumper cover (plastic) - Part #: 1L2Z-17K835-LA or equal	60	\$30700	% 27016	\$27016	\$1620960
Trunk lid - Part #: 6L2Z-7840010-AA or equal	20	\$8073	% 53321	\$53321	\$1066480
Radiator - Part #: 6L2Z-8005-ACP or equal	20	\$2582	% 18358	\$18358	\$367160