GENERAL NOTES

- CONTRACTOR SHALL VERIFY DIMENSIONS AND FIELD CONDITIONS, NOTIFY THE ARCHITECT OF ANY DISCREPANCIES IN CONTRACT DOCUMENTS, AND OBTAIN CLARIFICATION BEFORE PROCEEDING WITH WORK AFFECTED BY THE DISCREPANCIES.
- 2. FOLLOW FIGURED DIMENSIONS, AND DO NOT SCALE CONTRACT DRAWINGS.
- 3. PROVIDE TEMPORARY MARKERS FOR LINES AND LEVELS FOR USE BY ALL TRADES.
- 4. THESE DRAWINGS ARE TO BE USED IN CONJUNCTION WITH PROJECT SPECIFICATIONS.
- 5. PROVIDE TEMPORARY FENCING AND GATES TO RESTRICT UNAUTHORIZED ACCESS to the Job Site.
- 6. CONTRACTOR SHALL PROTECT ALL LANDSCAPE FEATURES (INCLUDING BUT NOT LIMITED TO TREES. SHRUBS. RAILINGS. AND WALKWAYS) PRIOR TO COMMENCING WITH WORK. CONTRACTOR SHALL SUBMIT A CONSTRUCTION PLAN REGARDING PROTECTION OF VEGETATION FOR REVIEW AND COORDINATION WITH THE GENERAL SERVICES DEPARTMENT.

REMOVAL NOTES

- CONTRACTOR SHALL PERFORM ALL OPERATIONS OF DEMOLITION AND REMOVAL INDICATED ON DRAWINGS AND AS MAY BE REQUIRED BY THE WORK. ALL WORK SHALL BE DONE CAREFULLY. NEATLY AND IN A SYSTEMATIC MANNER.
- 2. ALL EXISTING SURFACES AND EQUIPMENT TO REMAIN SHALL BE FULLY PROTECTED FROM DAMAGE. THE CONTRACTOR SHALL ASSUME FULL RESPONSIBILITY FOR DAMAGE AND SHALL MAKE REPAIRS REQUIRED WITHOUT ADDITIONAL COST TO THE OWNER.
- NO DEBRIS SHALL BE ALLOWED TO ACCUMULATE ON THE SITE. DEBRIS SHALL BE REMOVED 3 BY THE CONTRACTOR AS THE JOB PROCEEDS. THE SITE SHALL BE LEFT BROOM CLEAN AT THE COMPLETION OF DEMOLITION.
- NO STRUCTURAL ELEMENTS SHALL BE REMOVED UNLESS THE PORTIONS AFFECTED ARE ADEQUATELY SUPPORTED BY EITHER TEMPORARY SHORING OR NEW STRUCTURAL ELEMENTS AS REQUIRED TO PROTECT THE STABILITY AND INTEGRITY OF THE EXISTING STRUCTURE.
- STRUCTURAL DEMOLITION (IF REQUIRED) MUST BE PERFORMED UNDER STRICT SUPERVISION OF A STRUICTURAL ENGINEER HIRED BY THE CONTRACTOR.
- THE CONTRACTOR SHALL PROVIDE ADEQUATE WEATHER PROTECTION FOR THE BUILDING AND ITS CONTENTS DURING THE COURSE OF WORK.
- DISCOVERY OF ANY HAZARDOUS MATERIALS SHALL BE CONTAINED OR REMOVED AS REQUIRED BY PROPER AUTHORITIES.
- THE CONTRACTOR SHALL PROVIDE, ERECT AND MAINTAIN ALL TEMPORARY BARRIERS AND GUARDS AND ALL TEMPORARY SHORING AND BRACING AS REQUIRED BY THE DEPARTMENT OF BUILDINGS' RULES AND REGULATIONS.
- ALL ADJOINING PROPERTY AFFECTED BY ANY OPERATIONS OF DEMOLITION SHALL BE PROTECTED PER THE REQUIREMENTS THE DEPARTMENT OF BUILDINGS.

BUILDING DEPARTMENT NOTES

GENERAL DOB NOTES:

- ALL WORK SHALL BE PERFORMED IN ACCORDANCE WITH BUILDING REGULATIONS GOVERNING NOISE, WORK HOURS, AND SAFE DISPOSAL OF MATERIALS.
- MAINTAIN PROPER EGRESS FROM THE CONSTRUCTION SITE AT ALL TIMES.
- 3. ALL WORK SHALL BE PERFORMED BY CONTRACTORS LICENSED BY AUTHORITIES HAVING JURISDICTION.
- 4. CONTRACTOR SHALL OBTAIN ALL REQUIRED PERMITS AND CONTROLLED INSPECTIONS.
- 5. NO WORK AT SITE TO COMMENCE UNTIL PLAN HAS BEEN APPROVED AND PERMIT ISSUED BY DEPARTMENT OF BUILDINGS.

PROTECTION OF EXISTING PROPERTY:

- 6. ADJOINING PROPERTY AFFECTED BY WORK OPERATIONS SHALL BE PROTECTED.
- 7. THE CONTRACTOR SHALL BE SOLELY RESPONSIBLE FOR THE PROTECTION OF CONDITIONS AND MATERIALS WITHIN, AND ADJACENT TO THE PROPOSED CONSTRUCTION AREA.
- THE CONTRACTOR SHALL DESIGN AND INSTALL ADEQUATE SHORING AND BRACING FOR 8. CONSTRUCTION AND REMOVAL TASKS. SUBMIT SHORING DRAWINGS SIGNED & STAMPED BY A PROFESSIONAL ENGINEER LICENSED IN THE STATE OF WEST VIRGINIA.
- THE CONTRACTOR SHALL HAVE SOLE RESPONSIBILITY FOR DAMAGE AND INJURIES CAUSED BY, OR 9. DURING THE EXECUTION OF THE WORK.

SCOPE OF WORK:

- -MASONRY REPAIRS.
- -WOOD RESTORATION.
- -SLATE & FLAT SEAM COPPER ROOF REPLACEMENT AND REPAIRS.
- -INTERIOR DEMOLITION

SAFTEY NOTES

GENERAL :


DEBRIS, DIRT AND DUST SHALL BE CLEANED UP AND CLEARED FROM BUILDING DAILY TO AVOID EXCESSIVE ACCUMULATION.

EGRESS:

ALL EXISTING MEANS OF EGRESS FOR THE OCCUPANTS OF THE BUILDINGS SHALL BE MAINTAINED FREE OF ALL OBSTRUCTION SUCH AS BUILDING MATERIAL, TOOLS, ETC.

FIRE SAFTEY:

- ALL MATERIALS ARE TO STORED IN AN ORDERLY FASHION AND IN A MANNER TO AVOID CONCENTRATED LOADS ON TO THE BUILDING STRUCTURE.
- 4. ALL FLAMMABLE MATERIAL TO BE KEPT TIGHTLY SEALED IN THEIR RESPECTIVE MANUFATURER'S CONTAINERS. SUCH MATERIALS ARE TO KEPT AWAY FROM SOURCES OF HEAT.



MATERIALS INDICATIO	N
STONE	STEEL
BRICK	NEW CONSTRUCTION
WOOD	PATCH MATERI

DRAWING LIST

ARCHITECTURAL

	Т-0	COVER SHEET
	T-1	DRAWING LIST, LEGENDS, NOTES & QUANTITY OF
	D-101	CELLAR AND FIRST FLOOR SELECTIVE DEMOLITION
	D-101	SECOND AND THIRD FLOOR SELECTIVE DEMOLITION
	D=102 D=201	CELLAR AND FIRST FLOOR REFLECTED CEILING S
	D-201 D-202	SECOND AND THIRD FLOOR REFLECTED CEILING S
	A-100	ROOF PLAN
		SOUTH ELEVATION PORTICO
	A-201	
	A-201a	SOUTH ELEVATION
	A-202	EAST ELEVATION
	A-203	NORTH ELEVATION
	A-204	WEST ELEVATION
	A-501	REPAIR DETAILS: POINTING, SEALANT & BRICK
	A-502	REPAIR DETAILS: BRICK & MASONRY
	A-503	REPAIR DETAILS: MASONRY & LINTELS
	A-504	REPAIR DETAILS: WOOD TRIM
/	A-505	REPAIR DETAILS; WOOD TRIM
_	³ (A-506	REPAIR DETAILS: FLASHING (NOT USED))
	A-507	REPAIR DETAILS: FLASHING
	A-508	REPAIR DETAILS: ROOFING & FLASHING
	MECHAN	ICAL
	1	


MD-101	CELLAR/FIRST	FLOOR	MECHANICAL	DEMOLITION
MD-102	SECOND/THIRD	FLOOR	MECHANICAL	DEMOLITION

ELECTRICAL

ED-101	
ED-102	

CELLAR/FIRST FLOOR ELECTRICAL DEMOLITION PLANS SECOND/THIRD FLOOR ELECTRICAL DEMOLITION PLANS

ABB	REVIATIONS		
ADD'L ADJ. ALT.		N.I.C. NO.	NOT IN CONTRACT NUMBER
	APPROXIMATE	N.T.S. #	NOT TO SCALE NUMBER
AVG.	ANGLE (METAL)		
0	AT	0.C.	ON CENTER
B.O. Demo.	Bottom of Demolition, Demolish	P.L. Pt. Ptd.	Property line Paint Painted
DEPT. Det.	DEPARTMENT DETAIL	QTY.	QUANTITY
DIA. DIAG. DIM. DN.	DIAGONAL DIMENSION	RAD. RM. R.O.	ROOM
DR. DWG.	DOOR	SF	SQUARE FEET SQUARE INCH
EA.		SIM. SPEC.	SIMILAR
EL. Elec.	Elevation Electric(al)	SPEC. S.S. STRUC.	STAINLESS STEEL
EQ. (E)	EQUAL EXISTING	T.B.D.	to be determined
ÉXT. F.F.	exterior Finished Floor	TYP.	TYPICAL
FIXT. Fl.	fixture Floor	U.O.N.	UNLESS OTHERWISE NOTED
FT.	FOOT, FEET	VAR.	VARIES
HT.	HEIGHT	V.I.F.	VERIFY IN FIELD
IN.	INCH(ES)	W /	WIDTH
LF LTG.	Linear feet Lighting	W/ WD.	WITH
MAX.	MAXIMUM		
MECH.	MECHANICAL		
MFG.	MANUFACTUR(ING)(ER)		
MIN. MISC.	MINIMUM MISCELLANEOUS		
MISC. MTL.	METAL		




ORGANIZATION OF CONSTRUCTION DOCUMENTS

THE PROJECT CONSISTS OF THE REHABILITATION OF THE SUBJECT PREMISES AS DESCRIBED WITHIN THESE CONSTRUCTION DRAWINGS AND WITHIN THE PROJECT SPECIFICATIONS.

ON THE DRAWINGS EACH REQUIRED ARCHITECTURAL REPAIR IS IDENTIFIED BY A "REPAIR TAG." THE REPAIR TAGS ARE DIVIDED INTO TWO PARTS; 1)"REPAIR CODES" CONSISTING OF A COMBINATION OF ACRONYMS AND NUMBERS DESCRIBING THE MATERIAL AND TYPE OF REPAIR AND 2)"QUANTITY ESTIMATE" INDICATING A UNIT OF MEASURE AND AN ESTIMATED QUANTITY OF REPAIR. THE "REPAIR LEGEND" ON THE DRAWINGS TRANSLATES THE REPAIR CODES TO IDENTIFY THE MATERIAL TO BE REPAIRED AND THE TYPE OF REPAIR. THESE REPAIR CODES ARE FURTHER USED TO REFERENCE THE REPAIR DETAILS SHOWN ON THE DRAWINGS AS WELL AS EXECUTION OF THE REPAIRS AS DESCRIBED IN THE "PART 3-EXECUTION" SECTION OF THE APPLICABLE TECHNICAL SPECIFICATIONS.

QUANTITY ESTIMATES INDICATED IN THE REPAIR TAGS ARE APPROXIMATE AND ARE PROVIDED FOR THE CONTRACTOR'S BASE BID. THE CONTRACTOR IS RESPONSIBLE FOR VERIFYING ALL QUANTITIES IN FIELD. VARIATIONS FROM BASE BID QUANTITIES ARE TO BE ADJUSTED AT UNIT COST.

AS AN EXAMPLE, THE REPAIR TAG BELOW INDICATES REPAIR OF SEVEN (7) LINEAR FEET OF CRACKED LIMESTONE.



MISCELLANEOUS ITEMS AND ALL STRUCTURAL WORK IS IN ADDITION TO THE ARCHITECTURAL REPAIRS INDICATED BY REPAIR TAGS.

	ID	DESCRIPTION
	BR 01	BRICK CRACK REPAIR
	BR 02	BRICK SPALL REPAIR
	BR 03a	BRICK STITCHING
	BR 03b	BRICK STITCHING @ CHIMNEY
	CN 01	CONCRETE CRACK REPAIR WITH EPOXY
	CN 02	CONCR <u>ETE</u> SP <u>ALL</u> REPAIR
1		REPLACE FLASHING @ ALL 1815 HOUSE CH
		REPLACE STEP FLASHING @ DORMERS
7		REPLACE PERIMETER FLASHING
\langle	FL 04	COPPER GUTTER LINER REPLACEMENT
$\int_{\mathfrak{Z}}$	FL 05	COPPER GUTTER LINER @ SOUTH PORTICO
	LI 03a	NEW STEEL LINTEL REPLACEMENT @ CELLAF
	LI 03b	NEW STEEL LINTEL INSTALLATION & JACK A
	U 04	NEW STEEL LINTEL INSTALLATION @ WEST P
	PN 01	CHEMICAL STRIP AND PAINT WOOD
	PN 02	CHEMICAL STRIP AND PAINT WINDOW SASH
	PN 04	CHEMICAL STRIP AND PAINT STEEL W/ A R
	PN 05	CHEMICAL STRIP AND PAINT SHUTTER HINGE
	P0 01	BRICK REPOINTING
	P0 02	STONE REPOINTING
\checkmark	R0 (SL) 04	NEW SLATE ROOF
Ţ		NEW SLATE @ ALL DORMER FACES
5	(3L) 04a	
	R0 (SM) 04	NEW FLAT SEAMED COPPER SHEET METAL F
	RO (SM) 04	NEW FLAT SEAMED COPPER SHEET METAL F
	RO (SM) 04 RO 05	NEW FLAT SEAMED COPPER SHEET METAL F NEW PRECAST CONCRETE 30" SPLASH BLOO
	R0 (SM) 04 R0 05 SE 01	NEW FLAT SEAMED COPPER SHEET METAL F NEW PRECAST CONCRETE 30" SPLASH BLOO SEALANT REPLACEMENT @ BRICK/ CONCRET
	R0 (SM) 04 R0 05 SE 01 SE 02	NEW FLAT SEAMED COPPER SHEET METAL F NEW PRECAST CONCRETE 30" SPLASH BLOO SEALANT REPLACEMENT @ BRICK/ CONCRET SEALANT REPLACEMENT @ MASONRY/WOOD
	R0 (SM) 04 R0 05 SE 01 SE 02 SM 01	NEW FLAT SEAMED COPPER SHEET METAL F NEW PRECAST CONCRETE 30" SPLASH BLOO SEALANT REPLACEMENT @ BRICK/ CONCRET SEALANT REPLACEMENT @ MASONRY/WOOD NEW COPPER LEADER
	R0 (SM) 04 R0 05 SE 01 SE 02 SM 01 SM 02 ST 02	NEW FLAT SEAMED COPPER SHEET METAL F NEW PRECAST CONCRETE 30" SPLASH BLOO SEALANT REPLACEMENT @ BRICK/ CONCRET SEALANT REPLACEMENT @ MASONRY/WOOD NEW COPPER LEADER NEW COPPER STRAINER BASKET
	R0 (SM) 04 R0 05 SE 01 SE 02 SM 01 SM 02	NEW FLAT SEAMED COPPER SHEET METAL F NEW PRECAST CONCRETE 30" SPLASH BLOO SEALANT REPLACEMENT @ BRICK/ CONCRET SEALANT REPLACEMENT @ MASONRY/WOOD NEW COPPER LEADER NEW COPPER STRAINER BASKET STONE SPALL REPAIR W/ A COMPOSITE PA
	R0 (SM) 04 R0 05 SE 01 SE 02 SM 01 SM 02 ST 02 WD 01	NEW FLAT SEAMED COPPER SHEET METAL F NEW PRECAST CONCRETE 30" SPLASH BLOO SEALANT REPLACEMENT @ BRICK/ CONCRET SEALANT REPLACEMENT @ MASONRY/WOOD NEW COPPER LEADER NEW COPPER LEADER NEW COPPER STRAINER BASKET STONE SPALL REPAIR W/ A COMPOSITE PATCH
	R0 (SM) 04 R0 05 SE 01 SE 02 SM 01 SM 02 ST 02 WD 01 WD 02	NEW FLAT SEAMED COPPER SHEET METAL F NEW PRECAST CONCRETE 30" SPLASH BLOO SEALANT REPLACEMENT @ BRICK/ CONCRET SEALANT REPLACEMENT @ MASONRY/WOOD NEW COPPER LEADER NEW COPPER STRAINER BASKET STONE SPALL REPAIR W/ A COMPOSITE PAT WOOD REPAIR W/ COMPOSITE PATCH REPLACE TOP & BOTTOM RAIL OF RAILING
	R0 (SM) 04 R0 05 SE 01 SE 02 SM 01 SM 02 ST 02 WD 01 WD 02 WD 03	NEW FLAT SEAMED COPPER SHEET METAL F NEW PRECAST CONCRETE 30" SPLASH BLOO SEALANT REPLACEMENT @ BRICK/ CONCRET SEALANT REPLACEMENT @ MASONRY/WOOD NEW COPPER LEADER NEW COPPER LEADER NEW COPPER STRAINER BASKET STONE SPALL REPAIR W/ A COMPOSITE PATCH WOOD REPAIR W/ COMPOSITE PATCH REPLACE TOP & BOTTOM RAIL OF RAILING REPLACE POST @ SOUTH PORTICO
	R0 (SM) 04 R0 05 SE 01 SE 02 SM 01 SM 02 WD 01 WD 02 WD 03 WD 04	NEW FLAT SEAMED COPPER SHEET METAL F NEW PRECAST CONCRETE 30" SPLASH BLOO SEALANT REPLACEMENT @ BRICK/ CONCRET SEALANT REPLACEMENT @ MASONRY/WOOD NEW COPPER LEADER NEW COPPER STRAINER BASKET STONE SPALL REPAIR W/ A COMPOSITE PAT WOOD REPAIR W/ COMPOSITE PATCH REPLACE TOP & BOTTOM RAIL OF RAILING REPLACE POST @ SOUTH PORTICO REPLACE SELECTIVE SOFFIT ASSEMBLY
	R0 (SM) 04 R0 05 SE 01 SE 02 SM 01 SM 02 ST 02 WD 01 WD 02 WD 03 WD 05	NEW FLAT SEAMED COPPER SHEET METAL F NEW PRECAST CONCRETE 30" SPLASH BLOO SEALANT REPLACEMENT @ BRICK/ CONCRET SEALANT REPLACEMENT @ MASONRY/WOOD NEW COPPER LEADER NEW COPPER STRAINER BASKET STONE SPALL REPAIR W/ A COMPOSITE PAT WOOD REPAIR W/ COMPOSITE PATCH REPLACE TOP & BOTTOM RAIL OF RAILING REPLACE POST @ SOUTH PORTICO REPLACE SELECTIVE SOFFIT ASSEMBLY REPLACE SELECTIVE SOFFIT FASCIA
	R0 (SM) 04 R0 05 SE 01 SE 02 SM 01 SM 02 ST 02 WD 01 WD 02 WD 03 WD 05 WD 06	NEW FLAT SEAMED COPPER SHEET METAL F NEW PRECAST CONCRETE 30" SPLASH BLOO SEALANT REPLACEMENT @ BRICK/ CONCRET SEALANT REPLACEMENT @ MASONRY/WOOD NEW COPPER LEADER NEW COPPER STRAINER BASKET STONE SPALL REPAIR W/ A COMPOSITE PAT WOOD REPAIR W/ COMPOSITE PATCH REPLACE TOP & BOTTOM RAIL OF RAILING REPLACE POST @ SOUTH PORTICO REPLACE SELECTIVE SOFFIT ASSEMBLY REPLACE SELECTIVE SOFFIT FASCIA REPLACE FASCIA @ WEST PORCH
	R0 (SM) 04 R0 05 SE 01 SE 02 SM 01 SM 02 WD 01 WD 02 WD 03 WD 04 WD 05 WD 06 WD 07	NEW FLAT SEAMED COPPER SHEET METAL F NEW PRECAST CONCRETE 30" SPLASH BLOO SEALANT REPLACEMENT @ BRICK/ CONCRET SEALANT REPLACEMENT @ MASONRY/WOOD NEW COPPER LEADER NEW COPPER STRAINER BASKET STONE SPALL REPAIR W/ A COMPOSITE PAT WOOD REPAIR W/ COMPOSITE PATCH REPLACE TOP & BOTTOM RAIL OF RAILING REPLACE TOP & BOTTOM RAIL OF RAILING REPLACE SELECTIVE SOFFIT ASSEMBLY REPLACE SELECTIVE SOFFIT FASCIA REPLACE FASCIA @ WEST PORCH REPLACE FASCIA @ SOUTH PORTICO
	R0 (SM) 04 R0 05 SE 01 SE 02 SM 01 SM 02 WD 01 WD 02 WD 03 WD 04 WD 05 WD 06 WD 07 WD 08 WD 09	NEW FLAT SEAMED COPPER SHEET METAL F NEW PRECAST CONCRETE 30" SPLASH BLOO SEALANT REPLACEMENT @ BRICK/ CONCRET SEALANT REPLACEMENT @ MASONRY/WOOD NEW COPPER LEADER NEW COPPER STRAINER BASKET STONE SPALL REPAIR W/ A COMPOSITE PAT WOOD REPAIR W/ COMPOSITE PATCH REPLACE TOP & BOTTOM RAIL OF RAILING REPLACE TOP & BOTTOM RAIL OF RAILING REPLACE POST @ SOUTH PORTICO REPLACE SELECTIVE SOFFIT ASSEMBLY REPLACE SELECTIVE SOFFIT FASCIA REPLACE FASCIA @ WEST PORCH REPLACE FASCIA @ SOUTH PORTICO REPLACE FASCIA @ SOUTH PORTICO REPLACE FASCIA @ SOUTH PORTICO REPLACE FASCIA @ SOUTH PORTICO REPLACE FASCIA @ SOUTH PORTICO RE-ATTACH ENTABLATURE TRIM @ SOUTH P DUTCHMAN @ DORMER SILL REMOVE AND DISPOSE OF ALL WOOD SHUT
	R0 (SM) 04 R0 05 SE 01 SE 02 SM 01 SM 02 WD 01 WD 02 WD 03 WD 04 WD 05 WD 06 WD 07 WD 08 WD 09	NEW FLAT SEAMED COPPER SHEET METAL F NEW PRECAST CONCRETE 30" SPLASH BLOO SEALANT REPLACEMENT @ BRICK/ CONCRET SEALANT REPLACEMENT @ MASONRY/WOOD NEW COPPER LEADER NEW COPPER STRAINER BASKET STONE SPALL REPAIR W/ A COMPOSITE PAT WOOD REPAIR W/ COMPOSITE PATCH REPLACE TOP & BOTTOM RAIL OF RAILING REPLACE TOP & BOTTOM RAIL OF RAILING REPLACE POST @ SOUTH PORTICO REPLACE SELECTIVE SOFFIT ASSEMBLY REPLACE SELECTIVE SOFFIT FASCIA REPLACE FASCIA @ WEST PORCH REPLACE FASCIA @ SOUTH PORTICO REPLACE FASCIA @ SOUTH PORTICO
	R0 (SM) 04 R0 05 SE 01 SE 02 SM 01 SM 02 SM 02 WD 01 WD 02 WD 03 WD 05 WD 06 WD 07 WD 08 WD 09	NEW FLAT SEAMED COPPER SHEET METAL F NEW PRECAST CONCRETE 30" SPLASH BLOO SEALANT REPLACEMENT @ BRICK/ CONCRET SEALANT REPLACEMENT @ MASONRY/WOOD NEW COPPER LEADER NEW COPPER STRAINER BASKET STONE SPALL REPAIR W/ A COMPOSITE PAT WOOD REPAIR W/ COMPOSITE PATCH REPLACE TOP & BOTTOM RAIL OF RAILING REPLACE TOP & BOTTOM RAIL OF RAILING REPLACE POST @ SOUTH PORTICO REPLACE SELECTIVE SOFFIT ASSEMBLY REPLACE SELECTIVE SOFFIT FASCIA REPLACE FASCIA @ WEST PORCH REPLACE FASCIA @ SOUTH PORTICO REPLACE FASCIA @ SOUTH PORTICO REPLACE FASCIA @ SOUTH PORTICO REPLACE FASCIA @ SOUTH PORTICO REPLACE FASCIA @ SOUTH PORTICO RE-ATTACH ENTABLATURE TRIM @ SOUTH P DUTCHMAN @ DORMER SILL REMOVE AND DISPOSE OF ALL WOOD SHUT
	R0 (SM) 04 R0 05 SE 01 SE 02 SM 01 SU 02 WD 01 WD 02 WD 03 WD 04 WD 05 WD 06 WD 07 WD 08 WD 09 WD 10 WD 01	NEW FLAT SEAMED COPPER SHEET METAL F NEW PRECAST CONCRETE 30" SPLASH BLOO SEALANT REPLACEMENT @ BRICK/ CONCRET SEALANT REPLACEMENT @ MASONRY/WOOD NEW COPPER LEADER NEW COPPER STRAINER BASKET STONE SPALL REPAIR W/ A COMPOSITE PAT WOOD REPAIR W/ COMPOSITE PATCH REPLACE TOP & BOTTOM RAIL OF RAILING REPLACE TOP & BOTTOM RAIL OF RAILING REPLACE POST @ SOUTH PORTICO REPLACE SELECTIVE SOFFIT ASSEMBLY REPLACE SELECTIVE SOFFIT FASCIA REPLACE FASCIA @ WEST PORCH REPLACE FASCIA @ SOUTH PORTICO REPLACE FASCIA @ SOUTH PORTICO

^F REPAIRS)N PLANS ON PLANS SELECTIVE DEMOLITION PLANS SELECTIVE DEMOLITION PLANS

PLANS N PLANS

Swanke Hayden Connell Architects


Swanke Hayden Connell & Partners, LLP 295 Lafayette Street, New York, New York 10012 Phone 212 226 9696, Fax 212 219 0059

It is a violation of the law to alter this document in hard copy or electronic format (the "document") in any way. Use or modifications to this document is at the sole risk and liability of the user. The user shall, to the fullest extent of the law, hold SHCA harmless from any claims, liabilities or damages including legal fees that may be incurred as a result of any unauthorized or improper use or modification of

lo:	Date:	Revision:
	11-12-08	ISSUED FOR CBC REVIEW
	12-22-08	100% DRAFT
	02-13-09	100% FINAL
$\overline{1}$	04-16-09	
2	05-20-09	ADDENDUM # 6
3	06-05-09	3 ADDENDUM # 8
STA	TE OF	WEST VIRGINI
DEPAI	RTMENT OF	DIVISION OF
	ISTRATION	GENERAL SERVICE
	CHARLEST	ON, WEST VIRGINIA
		+ Virginia
	eston, Wes	t virginia
Holly	Grove Man	sion

NORTH

 \bigwedge



Swanke Hayden Connell Architects

Swanke Hayden Connell Ltd. Swanke Hayden Connell & Partners, LLP 295 Lafayette Street, New York, New York 10012 Phone 212 226 9696, Fax 212 219 0059

Structural Engineer:

CAS Structural Engineering, Inc. P.O. Box 469

Alum Creek, WV 25003


MEP Engineer:

CMA Engineering 824 Cross Lanes Drive

Charleston, WV 25313

It is a violation of the law to alter this document in hard copy or electronic format (the "document") in any way. Use or modifications to this document is at the sole risk and liability of the user. The user shall, to the fullest extent of the law, hold SHCA harmless from any claims, liabilities or damages including legal fees that may be incurred as aresult of any unauthorized or improper use or modification of this document.

Key Plan



Revision:

NORTH

11-12-08 ISSUED FOR CBC REVIEW _____ 12-22-08 100% DRAFT _____ 02-13-09 100% FINAL ____ 04-16-09 ADDENDUM # 6 05-20-09 <u>/2</u> ∕₃∖ 06-05-09 ADDENDUM # 8

Date:

STATE OF WEST VIRGINIA DEPARTMENT OF ADMINISTRATION CHARLESTON, WEST VIRGINIA

 Charleston, West Virginia

 BUILDING:

 Holly Grove Mansion

 PREJECT:

 SHCA PREJ. #: 6520-B

DRAWING TITLE:

Exterior Rehabilitation & Selective Demo.


DRAWING ND:

 Roof and Key Plan
 DATE:
 DATE:
 DATE:

 SJ/AR
 AS NOTED
 02/13/09
 A-100


 AL INFORMATION IN THIS DOCUMENT IS PROPERTY OF THE STATE OF VEST VIRCINIA AND SALE IN PART, VITHOUT THE
 CAD PATH SEQUENCE:

 EXAMPLE SO VARTIEN CONCERT OF THE STATE OF VEST VIRCINIA AND SALE IN PART, VITHOUT THE
 CAD PATH SEQUENCE:






WD 10 EA: 16 @ ALL WINDOWS



PN 01 SF: 380 ALL TRIM EXCEPT WINDOW FRAMES & DOORS


	REPAIR	LEGEND	
	MASONRY		POINTING & S
	BR 01 BR 02 BR 03a BR 03b CN 01	BRICK CRACK REPAIR BRICK SPALL REPAIR BRICK STITCHING BRICK STITCHING © CHIMNEY CONCRETE CRACK REPAIR WITH EPOXY	PO 01 PO 02 SE 01 SE 02
	CN 02 ST 02	CONCRETE SPALL REPAIR STONE SPALL REPAIR: COMPOSITE PATCH	PAINTING
	WOOD		PN 01
	WD 01 WD 02 WD 03	REPAIR W/ COMPOSITE PATCH REPLACE TOP/BOTTOM RAIL OF RAILING @ SOUTH ELEVATION REPLACE POST OF RAILING @ SOUTH ELEVATION	PN 04 PN 05
	WD 04 WD 05 WD 06	REPLACE SOFFIT ASSEMBLY REPLACE SOFFIT FASCIA REPLACE FASCIA @ WEST PORCH	ROOFING AND
•	WD 07 WD 08	REPLACE FASCIA @ SOUTH PORTICO RE-ATTACH ENTABLATURE TRIM @ SOUTH PORTICO	L FL 02 L FL 03
3	WD 09 WD 10 WD 11	DUTCHMAN @ DORMER SILL REMOVE AND DISPOSE OF WOOD SHUTTERS	FL 04 FL 05 RÔ (SL) 04
	LINTELS		RO (SL) 040
	LI 03a LI 03b LI 04	STEEL LINTEL REPLACEMENT STEEL LINTEL INSTALLATION & JACK ARCH RECONSTRUCTION NEW STEEL LINTEL INSTALLATION	RO 05 RO (SM) 04 SM 01

ADDITIONAL CONDITIONS ON



ADDITIONAL QUANTITIES:

IN ADDITION TO SPECIFIC LOCATIONS OF POINTING INDICATED ON DRAWING, CONTRACTOR TO INCLUDE AN ADDITIONAL <u>70 SF</u> OF BRICK REPOINTING (PO 01) ON THIS ELEVATION. LOCATIONS TO BE CONFIRMED WITH ARCHITECT. ANY QUANTITIES NOT USED MAY BE USED AT ARCHITECT'S AND OWNER'S DISCRETION AT OTHER ELEVATIONS. CONTRACTOR SHALL NOT BILL QUANTITIES NOT PERFORMED.



Swanke Hayden Connell Architects

Swanke Hayden Connell Ltd. Swanke Hayden Connell & Partners, LLP 295 Lafayette Street, New York, New York 10012 Phone 212 226 9696, Fax 212 219 0059

Structural Engineer:

CAS Structural Engineering, Inc. P.O. Box 469

Alum Creek, WV 25003


MEP Engineer:

CMA Engineering

824 Cross Lanes Drive Charleston, WV 25313

It is a violation of the law to alter this document in hard copy or electronic format (the "document") in any way. Use or modifications to this document is at the sole risk and liability of the user. The user shall, to the fullest extent of the law, hold SHCA harmless from any claims, liabilities or damages including legal fees that may be incurred as a result of any unauthorized or improper use or modification of this document.


Key Plan




NORTH

No: 	Date: 11-12-08 12-22-08 02-13-09 04-16-09 05-20-09	Revision: $ \frac{\text{ISSUED FOR CBC REVIEW}}{100\% \text{ DRAFT}} $ $ \frac{100\% \text{ FINAL}}{1} $ $ \frac{1}{2} \text{ ADDENDUM \# 6} $
DEPA	TE OT RTMENT (VISTRATIO CHARLE	OF DIVISION OF
BUILDING Holly PREJECT:	eston, W Grove M	est Virginia





			REPAIR TAG LEGEND		GEN
	POINTING &	SEALANT			1
	P0 01 P0 02	BRICK REPOINTING STONE REPOINTING		— MATERIAL CATEGORY	1. 1
	SE 01 SE 02	SEALANT REPLACEMENT @ BRICK/ CONCRETE JOINT SEALANT REPLACEMENT @ WOOD/ MASONRY JOINT			2. I
	PAINTING			- REPAIR TYPE	Founda
	PN 01 PN 04	CHEMICAL STRIP AND PAINT WOOD SCRAPE AND PAINT STEEL W/ A RUST INHIBITIVE COATING SCRAPE AND PAINT SHUTTER HINGERS W/ A RUST INHIBITVE			MEETS \
EVATION	PN 05	SCRAPE AND PAINT SHUTTER HINGERS W/ A RUST INHIBITVE COATING	RE (XX) ## SF: ##	- QUANTITIES OF REPAIR *	3. F
\wedge	ROOFING AND	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	WORK ITEM DESCRIPTION		WITH M.
<u> </u>	FL 01	- REPLACE STEP FLASHING @ CHIMNEY REPLACE STEP FLASHING @ DORMER			
\wedge	FL 03 FL 04	- REPLACE PERIMETER FLASHING COPPER GUTTER LINER REPLACEMENT	* QUANTITY ESTIMATES INDICATED IN THE REPAIR		
$\overline{3}$	R0 (SL) 04	REPLACE EASCIA AND GUTTER LINER @ SOUTH PORTICO	PROVIDED FOR THE CONTRACTOR'S BASE BID.		
	R0 (SL) 040	NEW PRECASI CONCRETE SU SPLASH BLOCK	FOR VERIFYING ALL QUANTITIES IN FIELD. VAR ARE TO BE ADJUSTED	IATIONS FROM BASE BID QUANTITIES	
RUCTION	RO (SM) 04 SM 01	NEW FLAT SEAMED COPPER SHEET METAL ROOF NEW COPPER LEADER AND STRAINER BASKET	AT UNIT COST.		
	•		1		L



			REPAIR TAG LEGEND		GENERAL NOTES
	POINTING &	SEALANT			
	P0 01 P0 02 SE 01 SE 02	BRICK REPOINTING STONE REPOINTING SEALANT REPLACEMENT @ BRICK/ CONCRETE JOINT SEALANT REPLACEMENT @ WOOD/ MASONRY JOINT		MATERIAL CATEGORY SPECIFIC MATERIAL (WHERE APPLICABLE)	 ALL REPLACEMENT WOOD ELEMENTS ARE TO MATCH EXISTING HISTORIC PROFILES. PERIMETER SEALANT IS TO BE APPLIED AT ALL WINDOW/ DOOR SURROUNDS. BASE SEALANT IS TO DE ADDUED AT ALL DEDIMETED
	Painting PN 01 PN 04 PN 05	CHEMICAL STRIP AND PAINT WOOD SCRAPE AND PAINT STEEL W/ A RUST INHIBITIVE COATING SCRAPE AND PAINT SHUTTER HINGERS W/ A RUST INHIBITVE COATING	RE (XX) ## SF: ## •	REPAIR TYPE UNIT OF MEASURE QUANTITIES OF REPAIR *	TO BE APPLIED AT ALL PERIMETER FOUNDATION MASONRY JOINTS AND WHERE MASONRY MEETS WOOD. 3. REMOVE AND REPLACE EXISTING CONDUIT & WIRES AS REQUIRED TO PERFORM WORK IN
3	COOFING AND L 01 L 02 L 03 L 04 L 05 C (SL) 04 C	FLASHING REPLACE STEP FLASHING © CHIMNEY REPLACE STEP FLASHING © DORMER REPLACE PERIMETER FLASHING COPPER GUTTER LINER REPLACEMENT REPLACE FASCIA AND GUTTER LINER © SOUTH PORTICO INSTALL NEW SLATE ROOF NEW SLATE © DORMER FACE NEW PRECAST CONCRETE 30 SPLASH BLOCK NEW FLAT SEAMED COPPER SHEET METAL ROOF NEW COPPER LEADER AND STRAINER BASKET	* QUANTITY ESTIMATES INDICATED IN THE RE PROVIDED FOR THE CONTRACTOR'S BASE FOR VERIFYING ALL QUANTITIES IN FIELD. ARE TO BE ADJUSTED AT UNIT COST.	BID. THE CONTRACTOR IS RESPONSIBLE	AFFECTED AREAS. COORDINATE WORK WITH M.E.P.

Swanke Hayden Connell Architects

Swanke Hayden Connell Ltd. Swanke Hayden Connell & Partners, LLP 295 Lafayette Street, New York, New York 10012 Phone 212 226 9696, Fax 212 219 0059

Structural Engineer:

CAS Structural Engineering, Inc. P.O. Box 469


Alum Creek, WV 25003 MEP Engineer:

CMA Engineering 824 Cross Lanes Drive

Charleston, WV 25313

It is a violation of the law to alter this document in hard copy or electronic format (the "document") in any way. Use or modifications to this document is at the sole risk and liability of the user. The user shall, to the fullest extent of the law, hold SHCA harmless from any claims, liabilities or damages including legal fees that may be incurred as a result of any unauthorized or improper use or modification of this document.

Key Plan




No:	Date:	Revision:
-	11-12-08	ISSUED FOR CBC REVIEW
-	12-22-08	100% DRAFT
	02-13-09	100% FINAL
	04-16-09	
2	05-20-09	ADDENDUM # 6
3	06-05-09	
DEPA	ATE OF ARTMENT OF INISTRATION	WEST VIRGINIA
	CHARLEST	TON, WEST VIRGINIA
BUILDIN	Gi	•
	<u>r Grove Mai</u>	NSION SHCA PROJ. #: 6520-I
		5

Exterior Rehabilitation & Selective Demo. DRAWING TITLE: DRAWING ND: North Elevation DATE |DRAWN BY: SCALE

AS NOTED 02/13/09 SJ/AR ALL INFORMATION ON THIS DOCUMENT IS PROPERTY OF THE STATE OF VEST VIRGINIA AND CAD PATH SEQUENCE: SHALL NUL BE REPORTINGED BE EXENSISED TO DITERSIN WHOLE OR IN PART, VITHOUT THE CARACLESY CONTENT OF THE STATE OF VESTIGATION OF THE STATE OF VIRGINIA








	REPAIR	LEGEND
	MASONRY	
	BR 01 BR 02 BR 03a BR 03b CN 01 CN 02	BRICK CRACK REPAIR BRICK SPALL REPAIR BRICK STITCHING BRICK STITCHING @ CHIMNEY CONCRETE CRACK REPAIR WITH EPOXY CONCRETE SPALL REPAIR
	ST 02 WOOD	STONE SPALL REPAIR: COMPOSITE PATCH
~	WD 01 WD 02 WD 03 WD 04 WD 05 WD 06 WD 07 WD 08	REPAIR W/ COMPOSITE PATCH REPLACE TOP/BOTTOM RAIL OF RAILING @ SOUTH ELEVAT REPLACE POST OF RAILING @ SOUTH ELEVATION REPLACE SOFFIT ASSEMBLY REPLACE SOFFIT FASCIA REPLACE FASCIA @ WEST PORCH REPLACE FASCIA @ SOUTH PORTICO
$\overline{3}$	WD 09 WD 10 WD 11	DUTCHMAN @ DORMER SILL REMOVE AND DISPOSE OF WOOD SHUTTERS REPLACEMENT OF WOOD SHEATHING
	LINTELS LI 03a LI 03b LI 04	STEEL LINTEL REPLACEMENT STEEL LINTEL INSTALLATION & JACK ARCH RECONSTRUCT NEW STEEL LINTEL INSTALLATION

06/05 W:\6520\B\DWG\03CD\PLOT\A-204_REVISED 09.06.05 ADDENDUM 8.DWG



Swanke Hayden Connell Architects

- BR 03b SF: 6 4502
- P0 01 SF: 20 1 A501
\sim
\$
WD 08 LF: 15 2 A505
- WD 07 LF: 13 1 A505
SM 01 LF: 25 2 A507
- WD 06 LF: 3 1 A-505
- LI 04 LF: 5 2 A-503
BR 03a SF: 23 AREAS INDICATED AND ABOVE DOOR FRAME
- PO 01 SF: 135 1 AT FRONT AND
 REVERSE FACES OF WALL
A501

ADDITIONAL QUANTITIES:

IN ADDITION TO SPECIFIC LOCATIONS OF POINTING INDICATED ON DRAWING, CONTRACTOR TO INCLUDE AN ADDITIONAL 100 SF OF BRICK REPOINTING (PO 01) ON THIS ELEVATION. LOCATIONS TO BE CONFIRMED WITH ARCHITECT. ANY QUANTITIES NOT USED MAY BE USED AT ARCHITECT'S AND OWNER'S DISCRETION AT OTHER ELEVATIONS. CONTRACTOR SHALL NOT BILL QUANTITIES NOT

GENERAL NOTES

ALL REPLACEMENT WOOD ELEMENTS ARE TO MATCH EXISTING HISTORIC PROFILES.

PERIMETER SEALANT IS TO BE APPLIED AT ALL WINDOW/ DOOR SURROUNDS. BASE SEALANT IS TO BE APPLIED AT ALL PERIMETER FOUNDATION MASONRY JOINTS AND WHERE MASONRY

> REMOVE AND REPLACE EXISTING CONDUIT & WIRES AS REQUIRED TO PERFORM WORK IN AFFECTED AREAS. COORDINATE WORK

Swanke Hayden Connell Ltd. Swanke Hayden Connell & Partners, LLP 295 Lafayette Štreet, New York, New York 10012 Phone 212 226 9696, Fax 212 219 0059

Structural Engineer: CAS Structural Engineering, Inc.

P.O. Box 469

Alum Creek, WV 25003


MEP Engineer:

CMA Engineering

824 Cross Lanes Drive Charleston, WV 25313

It is a violation of the law to alter this document in hard copy or electronic format (the "document") in any way. Use or modifications to this document is at the sole risk and liability of the user. The user shall, to the fullest extent of the law, hold SHCA harmless from any claims, liabilities or damages including legal fees that may be incurred as a result of any unauthorized or improper use or modification of this document.

Key Plan



NORTH

A-204

		$\mathbf{\mathbf{\mathbf{\mathbf{\mathbf{\mathbf{\mathbf{\mathbf{\mathbf{\mathbf{\mathbf{\mathbf{\mathbf{\mathbf{\mathbf{\mathbf{\mathbf{\mathbf{$					
No:	Date:	Revision:					
-	11-12-08	ISSUED FOR CBC REVIEW					
-	12-22-08	100% DRAFT					
	02-13-09	100% FINAL					
	04-16-09						
2	05-20-09	ADDENDUM # 6					
3	06-05-09	3 ADDENDUM # 8					
STA	ATE OF	WEST VIRGINIA					
גסיקת	RTMENT OF	DIVISION OF					
ADMI	NISTRATION	GENERAL SERVICES					
	CHARLEST	ON, WEST VIRGINIA					
		t Virginia					
Charleston, West Virginia							

Holly Grove Mansion SHCA PROJ. #: 6520-B Exterior Rehabilitation & Selective Demo. DRAWING ND: DRAWING TITLE

DATE

ALL INFORMATION ON THIS DOCUMENT IS PROPERTY OF THE STATE OF VEST VIRGINIA AND CAD PATH SEQUENCE: SHALL NUT BE REPORTINGED OF UNISED TO DIVERSION WHILE OF IN PART, VITHOUT THE EXPRESS VIRTITEN CONSENT OF THE STATE OF VEST VIRGINIA AND CAAD PATH SEQUENCE:

02/13/09


West Elevation


SCALE


AS NOTED

DRAWN BY

SJ/AR









Swanke Hayden Connell Architects


Swanke Hayden Connell Ltd. Swanke Hayden Čonnell & Partners, LLP 295 Lafayette Street, New York, New York 10012 Phone 212 226 9696, Fax 212 219 0059

Structural Engineer: CAS Structural Engineering, Inc. P.O. Box 469 Alum Creek, WV 25003

MEP Engineer: CMA Engineering 824 Cross Lanes Drive Charleston, WV 25313

It is a violation of the law to alter this document in hard copy or electronic format (the "document") in any way. Use or modifications to this document is at the sole risk and liability of the user. The user shall, to the fullest extent of the law, hold SHCA harmless from any claims, liabilities or damages including legal fees that may be incurred as a result of any unauthorized or improper use or modification of this document.

Key Plan



			NORTH
No:	Date:	Revision:	
_	11-12-08	ISSUED FOR CBC RE	\/IF\//
_	12-22-08	100% DRAFT	
	02-13-09	100% FINAL	
	04-16-09	ADDENDUM	# 6
$\frac{2}{3}$	<u>05-20-09</u> 06-05-09	3 ADDENDUM	
<u> </u>			
,			
ST	ATE OF	WEST V	IRGINIA
			1100110111
	RTMENT OF		SION OF
ADMI	NISTRATION	GENEL	RAL SERVICES
	CHARLES:	TON, WEST VIR	GINIA
Char BUILDING	<u>leston, We</u>	st Virginia	
Holly	<u>y Grove Ma</u>	nsion	
		ion & Selective I	а рац. #: 6520-в Demo.
DRAWING	i TITLE:		DRAWING ND:
Deta DRAWN B	IS: Flashing	DATE:	A-507
SJ/AR	AS NOTE	ED 02/13/09	
ALL INFORMATIC SHALL NOT BE EXPRESS WRITT	IN ON THIS DOCUMENT IS PROPERTY REPRODUCED OF FURNISHED TO OTH EN CONSENT OF THE STATE OF VES	of the state of vest virginia and ers,in whole or in part, vithout the st virginia.	CAD PATH SEQUENCE: C:\ACAD\SUPPORT\SHEETS\D-SHEET

<u>NOTES:</u>

1. CONTRACTOR IS REPONSIBLE FOR COORDINATING WORK WITH GUTTER LINER REPLACEMENT (FL 04). SEE DETAIL 1/A-507.

2. NEW WOOD FASCIA TO BE PRESSURE TREATED, EXTERIOR GRADE LUMBER. 3. PREPARE ALL ADJACENT EXISTING MATERIAL TO RECEIVE NEW WOOD

FASCIA UNITS.

4. PREP AND PRIME SURFACE OF NEW FASCIA BOARD FOR PAINT.

